| Μ | es | sa | ge |
|---|----|----|----|
|---|----|----|----|

| From: | Nonresponsive based on revised scope | |
|--------------|---|--|
| Sent: | 8/2/2019 5:18:08 PM | |
| То: | Nonresponsive based on revised scope ; Wagner, Christine [Wagner.Christine@epa.gov]; Duffy, | |
| | Jessica [Duffy.Jessica@epa.gov] Nonresponsive based on revised scope | |
| CC: | Nonresponsive based on revised scope | |
| Subject: | Shiloh | |
| Attachments: | Conex Survey 190801.pdf; Contamination_Control_07312019.pdf | |

Attached are the forms from last week, including:

- Conex Survey on Thursday, 8/1/19, at end of day. Greatest exterior reading was 305 uR/hour. Front of conex and general storage conex readings were 45 and 27 uR/hour, respectively.
- Contamination Control Survey collected on Wednesday , 7/31/19. No removable contamination was found on areas in the support zone

Please let me know if you have any questions.

Thanks, Nonresponsive based on revised scope

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.